

IMPORTANT SAFETY RECALL

BOSTITCH Model BTE140 and BTE141 Hammer Drills

The side handle can slip and could lead to the loss of control of the tool and injury to the user.

The affected side handles were supplied with Model BTE140 and BTE 141 Hammer Drills with date codes prior to 2018 22-58-XX

Check the side handle on your hammer drill to see if it is affected



If your hammer drill is affected, **STOP USING IT IMMEDIATELY**, and call toll free to receive a free replacement side handle

1-888-284-3070

between 8 a.m. and 5 p.m., Eastern Time, Monday through Friday,
or e-mail: recall@sbdinc.com.